
BLACKHAWK

REPAIR PARTS SHEET
HAND JACK
MODEL AA-8.5E
RATED CAPACITY
5-TON

Sheet No. S-108 Issued February, 1959



REPAIR PARTS SHEET FOR AA-8.5E HYDRAULIC JACK

•

Parts List on Reverse Side

REPAIR PARTS LIST FOR AA-8.5E JACK

item No.	-	No. Part Name Req
I AA85.05P-4		Base
2	1.16	Valve Ball
3	\$1.16	Valve Ball1
4	BA85.183	Outlet Valve Spring
5	B159.167	Valve Plug Gasket
6	CB9.185-1	Valve Plug
7	CB9.335	Release Valve Packing Washer I
8	1.74	Release Valve Packing
9	CB9.11-1	Release Valve Packing Nut
10	BA85.10A-1	Release Valve Spindle
11	B155.026	Name Plate
12	W78.03	Drive Screw4
13	BA85.18-1	Oil Strainer Screen
14	AA85.30-3	Cylinder
15	AA85.40-3	Plunger
16	AA85.39	Plunger Sleeve
17	AA85.28-1	Plunger Adjusting Screw
18	AA85.45-1	Saddle
19	AA85.29-2	riunger King
20	M73.41-1	Plunger Cup Washer
21	AA85.45	Plunger Cup Retaining Nut
22	AA85,120	Reservoir
23	C0 27	Filler Plug Gasket
24 25	CO 22 I	Filler Plug
25	A A OF 20 2	Top Cap
	CALL 74	Plunger Packing2
27 28	AA95 21	Gland Nut
29	CRO 51-1	Pump Plunger
30	E11 K3	Pump Cup

ite: No		No. Part Name Req
31	F11.52	Pump Cup Spreader
32	CB9.55	Pump Cup Retaining NutI
33	CB9.50-1	Pump Cylinder
34	5.75	Pump Packing2
35	CB9.54-1	Pump Gland Nut
36	CR9 A0-2	Beam
37	CB9.61-2	Beam Handle Pin
38	CB9.57-1	Beam Pin1
39	1.58	Cotter Pin3
40	BA85.57-1	Base Link Pin2
41	BA85.62-2	Link
	H12	Handle
		Blackhawk Oil No. LX21 5/8 Pt. (17 Cu. In.)
	CJ100.038	Decal
		SUB-ASSEMBLIES
	AA85.05C-4	Tested Base items 1 thru 6
	AA85.40C-3	Complete Plunger items 15 thru 22 incl
	CB9.50A-1	Pump Assembly Complete
		items 29 thru 35 incl
	CB9.51A-1	Pump Plunger Complete items
		29 thru 32 incl
	CB9.60A-2	Beam & Link Complete items
		36 thru 41 incl
	CB9.60B-2	Beam & Beam Handle Pin
		items 36 & 37

NOTE: Orders for parts cannot be filled unless both model and serial number with prefix, imprinted on nameplate of ram, are given.

GUARANTEE

Blackhawk guarantees its Hand Jacks, Service Jacks and Porto-Power against defects in workmanship and material for 90 days from date of delivery to the user. Only exception is Porto-Power chain, which follows the trade custom of its manufacturers and cannot be guaranteed.

When question of warranty arises, the user should send his unit to the nearest Blackhawk Franchised Service Depot for inspection, or to the Blackhawk Service Division, 5054 W. State St., Milwaukee 8, Wis.; transportation to be prepaid and evidence of delivery date furnished.

If the difficulty comes under the terms of our guarantee, we will repair or replace parts affected and return prepaid. Our guarantee does not cover ordinary wear and tear, abuse, misuse, overloading, altered products or use of improper fluid.

A Network of FRANCHISED SERVICE DEPOTS serves Blackhawk Users worldwide

For quality workmanship with genuine Blackhawk parts select a franchised Blackhawk Service depot for your repair work. Only repairs performed by a franchised service depot are backed with full factory guarantee. The Classified Section in your Phone Book lists your nearest Franchised Service Depot.

BLACKHAWK MFG. CO. - - - MILWAUKEE 46, WIS.