
Master Copy

BLACKHAWK

REPAIR PARTS SHEET
HAND JACK
MODEL FB-11C
RATED CAPACITY
30-TON

Sheet No. 1115 Issued February, 1959



REPAIR PARTS SHEET FOR FB11-C HAND JACK FRANCHISED SERVICE DEPOT BLACKHAWK

Parts List on Reverse Side

PARTS LIST FOR MODEL FB11-C

Item No.	Part No.	No. Req.	Item No.	Part No.	No. Req.
1	FBII.05 Base		36	GB11.54	Pump Plunger Packing
1 7	FB11.511'O' Ring				Nut1
3	FBI 1.30 Cylinder		37	GB11.51	Speed Pump Plunger
4	NI2.212 Dowel Pin		38	N12.233	
5	FB11.107 Rod		39		V-Cup Spreader
6	GBI 1.395 Valve Spacer			GB11.53	
7	1.16Ball, 7/32" Dia.		41	GB11.53R	
8	\$8.255 Spring			GB11.187	Plunger Packing Nutt
9	N12.340Spring Retainer		43	GB11./5	Pump Plunger Packing3
10	FB11.71-1 Disc		44	GB11.55	
	W293.504 'O' Ring		46	M129.281 N12.169	
	FBII.317 Leather Washer		1	N12.169	
12	FAII.41-IPlunger Cup				O'Ring
13	FBII.43Spreader		49	GRI 1 525	O' Ring Fastener Plate
	FBII.40APlunger		50	GB11.526	Screw 3
15	FBI 1.25A Reservoir		51	GB11.57	Beam Handle Pin
16	FBII.20Top Cap				.Nut
17	FAII.76 Plunger Packing FAII.21 Gland Nut		53	N12.28	Adjusting Screw
19	B159.167 Gasket			FB11.06	Base Plug
1 ' '			55	GB11.74	Release Valve Packing 3
21	FBII.150AFiller Plug Gauge		56	GBII.II	Release Valve Packing
	B160.274 Safety Valve Needle				Nut
23	\$13.144 Overflow Value Casin		57	GBII.IOA	Release Valve Spindle 1
24	S13.164 Overflow Valve Spring	91			Pipe Plug
25	P170.185B-1 Valve Plug E14.16 Ball, 9/32" Dia.	2	59		Name Plate
26	W12.16Ball, 38" Dia.		60	W78.03	Drive Screw2
27	P26.183 Outlet Valve Spring				
28	GBII.186AValve Spacer				SUB-ASSEMBLIES
	FBI 1.18 Oil Strainer Screen			CRILION	Sanad Burn Ounday Value
	GBII.167Gasket			GD11.170L	Speed Pump Overflow Valve (includes Items 21, 22, 23
31	GBII.150Oil Sealing Plug	······································			and 24)
32	GBII.163Pump Plunger Guide	******		CRILEIA	
33	NI2.52V-Cup Spreader			GBII.5IA	Speed Pump Plunger Assembly
34	DA67.53 V-Cup				(includes Items 33, 34, 35,
35	GBII.192 Inner Pump Cup Space				36, 37 and 38)
	Out 1.172 miler rump Cup Space	CI I			

NOTE: Orders for parts cannot be filled unless both model and serial number with prefix, imprinted on nameplate of ram, are given.

GUARANTEE

Blackhawk guarantees its Hand Jacks, Service Jacks and Porto-Power against defects in workmanship and material for 90 days from date of delivery to the user. Only exception is Porto-Power chain, which follows the trade custom of its manufacturers and cannot be guaranteed.

When question of warranty arises, the user should send his unit to the nearest Blackhawk Franchised Service Depot for inspection, or to the Blackhawk Service Division, 5054 W. State St., Milwaukee 8, Wis.; transportation to be prepaid and evidence of delivery date furnished.

If the difficulty comes under the terms of our guarantee, we will repair or replace parts affected and return prepaid. Our guarantee does not cover ordinary wear and tear, abuse, misuse, overloading, altered products or use of improper fluid.

A Network of FRANCHISED SERVICE DEPOTS serves Blackhawk Users worldwide

For quality workmanship with genuine Blackhawk parts select a franchised Blackhawk Service depot for your repair work. Only repairs performed by a franchised service depot are backed with full factory guarantee. The Classified Section in your Phone Book lists your nearest Franchised Service Depot.

BLACKHAWK MFG. CO. - - - MILWAUKEE 46, WIS.