

REPAIR PARTS SHEET FOR R-75-1 PORTO-POWER RAM

REPAIR PARTS SHEET FOR R-75-1 PORTO-POWER RAM

Item No.	Part No.	Part Name	No. Req'd.	Item No.	Part No.	Part Name	No. Req'd.
1	W7803	Drive Screw	2	* 9	R28.41	Plunger Cup	1
2	R75.900	Base	1	10	R33.43	Spreader	1
3	R75.20	Top Cap	1	11	R33.44	Stop Ring	1
4	B155.026	Name Plate			R75.902	Saddle	1
* 5	R33.35	Plunger Cup Nut	1	13	R28.271	Thread Protector	1
6	R75.901	Male Adapter			R28.280	Spring Washer	1
7	R75.40	Plunger			R28.316	Cup Separator	2
*8	R16.41 ×	Plunger Cup					

K75T Repair Kit - Includes Items Marked * Above

NOTE: No orders for parts can be filled unless both model and serial number with prefix, imprinted on nameplate of ram, are given.

GUARANTEE

Blackhawk guarantees its Hand Jacks, Service Jacks and Porto-Power against defects in workmanship and material for 90 days from date of delivery to the user. Only exception is Porto-Power chain, which follows the trade custom of its manufacturers and cannot be guaranteed.

When question of warranty arises, the user should send his unit to the nearest Blackhawk Franchised Service Depot for inspection, or to the Blackhawk Service Division, 5054 W. State St., Milwaukee 8, Wis.; transportation to be prepaid and evidence of delivery date furnished.

If the difficulty comes under the terms of our guarantee, we will repair or replace parts affected and return prepaid. Our guarantee does not cover ordinary wear and tear, abuse, misuse, overloading, altered products or use of improper fluid.

A Network of AUTHORIZED REPAIR STATIONS serves Blackhawk Users worldwide

For quality workmanship with genuine Blackhawk parts select an authorized Blackhawk Service Station for your repair work. Only repairs performed by an authorized service station are backed with full factory guarantee. The Classified Section in your Phone Book lists your nearest Authorized Service Station.

BLACKHAWK MFG. CO. - - - MILWAUKEE 46, WIS.