BLACKHAWK

Porto-Power

Body Repair Equipment


Repair Parts Information

"Spred" Rams

MODELS SA-8 & SA-10

Serial Code A

CAPACITY: 1 TON



REPAIR PARTS LIST

Item No.		No. Req.	Description
1	K1.103	2	Arm
2	K55.061	4	Pin
3	SJ18.545	10	Ring
4	K56.061	2	Pin
5	K6.186	4	Spacer
6	K8.062	4	Link
7	K16.110	4	Spring
8	K54.061	1	Pin
9	R590.40	1	Plunger
10	B627.044	1	Ring
11	R159.71	1	Disc
* 12	R159.41	2	Cup (Leather)
* 13	R159.316	2	Separator
* 14	B175.041	1	Cup (Rubber)
15	R159.43-1	1	Spreader
16	R159.280	1	Washer
17	R159.35-1	1	Nut
18	R590.900	1	Base
19	K1.039	1	Reducer, 3/8" to 1/4"
20	ZR-400	1	Coupler Ram Half (SA-8)
	ZR-630	1	Coupler Ram Half (SA-10)
21	Z.410-1	1	Cover (SA-8)
	Z.640-1	1	Cover (SA-10)
22	ZH-604	1	Coupler Hose Half (SA-8)
	ZH-630	_ 1	Coupler Hose Half (SA-10)
23	Z-604	1	Coupler Complete (SA-8)
	Z-630	1	Coupler Complete (SA-10)
† 24	Z-909	1	6' Hose (SA-8)
	Z-624	1	6' Hose (SA-10)
† 25	ZR.400X		Coupler Kjt (SA-8)
† 26	ZR.630X		Coupler Kit (SA-10)
† 27	LX-21		Special Oil
t Not S			
For e	conomical n included in		ance order Repair Kit SA.008X.

NOTE: Orders for parts cannot be filled unless both model and serial number with prefix imprinted on nameplate are given.

WARRANTY

Blackhawk warrants its repair parts against defects in workmanship and materials for 90 days from date of delivery to user. Chain is not warranteed. Warranty does not cover ordinary wear and tear, abuse, misuse, overloading, altered products or use of improper fluid.

WARRANTY RETURN PROCEDURE

When question of warranty claim arises, the user should send his unit to the nearest Blackhawk Authorized Service Depot for inspection, transportation to be prepaid and evidence of purchase date furnished. If the claim comes under the terms of our warranty, the Authorized Service Depot will REPAIR OR REPLACE PARTS AFFECTED and return prepaid.

BLACKHAWK

BLACKHAWK MFG. CO., MILWAUKEE, WIS. 53227 DIVISION OF APPLIED POWER INDUSTRIES, INC.