

# BLACKHAWK®

REPAIR PARTS SHEET



**HAND JACK  
MODEL AA 8.5-C**

RATED CAPACITY  
5-TON

Sheet No. 1096

Issued February, 1959

Supersedes Sheet No. 720K



**REPAIR PARTS SHEET FOR AA 8.5-C  
HYDRAULIC JACK**



Parts List on Reverse Side



# PARTS LIST FOR MODEL AA 8.5-C

Item No.	Part No.	Part Name	No. Req.
1	W78.03	Drive Screw	2
2	AA8.505P-2	Base	1
3	Not Used		
4	CB9.10	Release Valve Spindle	1
5	CB9.11	Release Valve Packing Nut	1
6	1.16	7/32" Ball	1
7	51.16	5/16" Ball	1
8	BA8.518	Oil Strainer Screen	1
9	AA10.20-1	Top Cap	1
10	C8.521	Gland Nut	1
11	C9.22	Filler Plug	1
12	AA8.525-1	Reservoir	1
13	BA8.526	Name Plate Transfer	1
14	1.26E	Name Plate	1
15	AA8.528	Plunger Adjusting Screw	1
16	AA10.29	Plunger Plug	1
17	AA8.530-1	Cylinder	1
18	1.33-1	Plunger Cup	1
19	C9.37	Filler Plug Gasket	1
20	AA8.540-1	Plunger	1
21	CA11.42	Plunger Cup Retaining Screw	1
22	5.43	Spreader	1
23	AA10.45	Saddle	1
24	AA10.50	Pump Cylinder	1
25	AA10.51	Pump Plunger	1
26	E11.52	Pump Cup Spreader	1
27	E11.53	Pump Cup	1
28	AA10.54	Pump Gland Nut	1
29	AA10.55	Pump Cup Retaining Nut	1

Item No.	Part No.	Part Name	No. Req.
30	CB9.57	Beam Pin	2
31	1.58	Cotter Pin	2
32	CB9.60-1	Beam	1
33	S4.61	Release Valve Spindle Pin	1
34	CB9.61	Beam Handle Pin	1
35	CB9.62-1	Link	1
36	CB9.63	Link Rivet	1
37	1.74	Release Valve Packing	1
38	1.75	Pump Packing	2
39	1.76	Plunger Packing	2
40	B159.167	Valve Plug Gasket	1
41	S1.183	Outlet Valve Spring	1
42	CB9.185	Valve Plug	1
43	CB9.335	Release Valve Packing Washer	1
	H-9	Jack Handle (two-piece 34" long)	1
		Blackhawk Hydraulic Oil #30 17 Cu. In. (about 5/8 pint)	
		SUB-ASSEMBLY	
	AA8.540C-1	Plunger Assembly (Includes Items 15, 16, 20 and 23)	
		NEVER Use Hydraulic Brake Fluid	

**NOTE:** Orders for parts cannot be filled unless both model and serial number with prefix, imprinted on nameplate of ram, are given.

## GUARANTEE

Blackhawk guarantees its Hand Jacks, Service Jacks and Porto-Power against defects in workmanship and material for 90 days from date of delivery to the user. Only exception is Porto-Power chain, which follows the trade custom of its manufacturers and cannot be guaranteed.

When question of warranty arises, the user should send his unit to the nearest Blackhawk Franchised Service Depot for inspection, or to the Blackhawk Service Division, 5054 W. State St., Milwaukee 8, Wis.; transportation to be prepaid and evidence of delivery date furnished.

If the difficulty comes under the terms of our guarantee, we will repair or replace parts affected and return prepaid. Our guarantee does not cover ordinary wear and tear, abuse, misuse, overloading, altered products or use of improper fluid.

## A Network of FRANCHISED SERVICE DEPOTS serves Blackhawk Users worldwide

For quality workmanship with genuine Blackhawk parts select a franchised Blackhawk Service depot for your repair work. Only repairs performed by a franchised service depot are backed with full factory guarantee. The Classified Section in your Phone Book lists your nearest Franchised Service Depot.

**BLACKHAWK MFG. CO. - - - MILWAUKEE 46, WIS.**