


10 TON RAM

Item No.	Part No.		No. Req.	Description
	† Model K256.900 6" Stroke	† Model K257.900 10" Stroke		
69	R159.184	B12.184	1	Spring
70	B7.209	B7.209	1	Bushing
71	B633.302	B633.302	1	Screw
†72	K262.005	K253.005	1	Base
73	K4.028	K4.028	1	Screw
74	ZR-400	ZR-400	1	Coupler (Ram Half)
**74	ZH-604	ZH-604	1	Coupler (Pump Half)
**74	Z-604	Z-604	1	Coupler Complete
75	Z-410-1	Z-410-1	1	Cover
76	C611.049	C611.049	1	Ring
77	F942.108	F942.108	1	Washer
*78	Cup			Order Kit K256.900X
*79	Wiper			Order Kit K256.900X
80	G384.108	G384.108	1	Washer
81	G382.107	G382.107	2	Bearing
82	J929.044	J929.044	1	Ring
*83	Wiper			Order Kit K256.900X
84	G385.044	G385.044	1	Ring
85	G831.446	G831.446	1	Sleeve
86	K261.040	K252.040	1	Plunger
87	Z-914	Z-914	1	Hose w/Z-604
88	Z-913	Z-913	1	Hose w/ZH-604
89	Z-909	Z-909	1	Hose, 6'
**90	E740.026	E740.026	1	Decal (Repair)

For economical maintenance order Repair Kit K256.900X  
Items included in Kit are marked with asterisk (\*).

\*\*Not Shown.

†Order from franchised Korek distributor or Blackhawk Mfg. Co.



**NOTE:** Orders for parts cannot be filled unless both model and serial number with prefix imprinted on nameplate are given.

### WARRANTY

Blackhawk warrants its replacement parts against defects in workmanship and materials for 90 days from date of delivery to user. Chain is not warranted. Warranty does not cover ordinary wear and tear, abuse, misuse, overloading, altered products or use of improper fluid.

### WARRANTY RETURN PROCEDURE

When question of warranty claim arises, the user should send his unit to the nearest Blackhawk Authorized Service Depot for inspection, transportation to be prepaid and evidence of purchase date furnished. If the claim comes under the terms of our warranty, the Authorized Service Depot will REPAIR OR REPLACE PARTS AFFECTED and return prepaid.

# BLACKHAWK®