




TEMPLETON, KENLY & CO.


2525 Gardner Road • Broadview, Illinois 60153 • 312-865-1500

REPAIR PARTS SHEET FOR Simplex Steamboat Ratchet Jacks — "ER" Series

07151 **ER10** 07201 **ER30**
07176 **ER20** 07282 **ER40**



| ITEM NO. | JACK NO. 07151 ER10 CONTROL NO. | JACK NO. 07176 ER20 CONTROL NO. | JACK NO. 07201 ER30 CONTROL NO. | JACK NO. 07282 ER40 CONTROL NO. | NAME OF PART |
|----------|---------------------------------------|---------------------------------------|---------------------------------------|---------------------------------------|---|
| 1 | * | --- | --- | --- | Pipe Barrel (3 In. Std. Pipe, L=17½ In.) |
| 1 | --- | * | --- | --- | Pipe Barrel (3 In. Std. Pipe, L=23½ In.) |
| 1 | --- | --- | * | --- | Pipe Barrel (3 In. Std. Pipe, L=29½ In.) |
| 1 | --- | --- | --- | * | Pipe Barrel (3 In. Std. Pipe, L=41½ In.) |
| 2R | * | * | * | * | Nut, Right Hand |
| 2L | * | * | * | * | Nut, Left Hand |
| 3 | * | * | * | * | Ratchet Wheel |
| 4 | 91448 | 91557 | 91564 | 91451 | Pipe Barrel Complete (Includes Items 1, 2L And 3) |
| | 91452 | --- | --- | --- | Screw, 2 In. Dia. L=11 In. W=3½ In., Right Hand |
| 5L | 95265 | --- | --- | --- | Screw, 2 In. Dia. L=11 In. W=3½ In., Left Hand |



WARRANTY

Templeton, Kenly & Co. warrants to the purchaser of its products that if the product or any part thereof in the judgment of Templeton, Kenly & Co. is proven to be defective in material or workmanship within one year from the date of original purchase (two years on Heavy Duty Hydraulics and five years on Super Jacks), such defects will be repaired or replaced (at the company's option) free of charge for parts and labor.

This warranty does not apply to any product which has been damaged by accident or which has been misused, abused, altered, or repaired by anyone other than recognized Templeton, Kenly authorized Service Centers.

This warranty is in lieu of all other warranties expressed or implied, and no other person is authorized to assume for Templeton, Kenly & Co. any other liability in connection with the sale of this product.

TEMPLETON, KENLY & CO.

2525 Gardner Road • Broadview, Illinois 60153

| ITEM NO. | JACK NO. 07151 ER10 CONTROL NO. | JACK NO. 07176 ER20 CONTROL NO. | JACK NO. 07201 ER30 CONTROL NO. | JACK NO. 07282 ER40 CONTROL NO. | NAME OF PART |
|----------|---------------------------------------|---------------------------------------|---------------------------------------|---------------------------------------|--|
| 5R | ---- | 91583 | ---- | ---- | Screw, 2 In. Dia. L=14 In. W=3½ In. Right Hand |
| 5L | ---- | 95252 | ---- | ---- | Screw, 2 In. Dia. L=14 In. W=3½ In. Left Hand |
| 5R | ---- | ---- | 91584 | ---- | Screw, 2 In. Dia. L=17 In. W=3½ In. Right Hand |
| 5L | ---- | ---- | 95254 | ---- | Screw, 2 In. Dia. L=17 In. W=3½ In. Left Hand |
| 5R | ---- | ---- | ---- | 91467 | Screw, 2 In. Dia. L=23 In. W=3½ In. Right Hand |
| 5L | ---- | ---- | ---- | 95253 | Screw, 2 In. Dia. L=23 In. W=3½ In. Left Hand |
| 6 | 91522 | 91522 | 91522 | 91522 | Ratchet Pawl |
| 7 | 93567 | 93567 | 93567 | 93567 | Ratchet Pawl Hex. Hd. Cap Screw |
| 7A | 93642 | 93642 | 93642 | 93642 | Ratchet Pawl Hex. Jam Nut |
| 8 | 91548 | 91548 | 91548 | 91548 | Socket (Set of 2) |
| 9 | 93539 | 93539 | 93539 | 93539 | Socket Hex. Hd. Cap Screw (2 Required) |
| 9A | 93850 | 93850 | 93850 | 93850 | Socket Hex. Nut (2 Required) |
| 10 | 91523 | 91523 | 91523 | 91523 | Pawl Plunger |
| 11 | 91524 | 91524 | 91524 | 91524 | Pawl Plunger Spring |
| 12 | 91525 | 91525 | 91525 | 91525 | Lever Bar |

*Indicates Parts Sold In Assemblies Only.

In ordering, specify the CONTROL NUMBER, NAME OF PART and JACK NUMBER.